

EcoBest™ Gel Stripper Installation Guide



EcoBest™ GEL Stripper Advantages:

- Fast Acting Gel Formula
- Removes Multiple Layers
- Penetrates & Lifts
- Works by Delamination
- Easier Residue Cleanup
- Low Odor
- Biodegradable
- Bio-Based
- Renewable Ingredients
- Low V.O.C.'s < 50 g/L

Typical Uses:

Lead Paint, Latex Paint,
Varnishes, Sealers, Epoxy
Coatings, Stains, Polyure-
thanes, Polyaspartics,
Enamels, Powder Coat-
ings, Tile & Carpet Adhe-
sives and more...



Manufactured By



Made in the U.S.A.

EcoBest™ GEL Stripper is the latest breakthrough in solvent replacement cleaning technology used to safely strip multiple layers of paint, coatings, and adhesives. EcoBest™ GEL is a powerful non-hazardous, non-flammable, biodegradable, eco-friendly paint stripper formulated with a thick gel-like viscosity for optimum cling on vertical or horizontal surfaces to allow uniform coverage and optimum dwell time. The solution will remain active up to 24 hours.

DIRECTIONS: Always test surfaces for applicable application thickness, dwell times, and substrate compatibility. Mask surfaces not intended to be stripped and protect plants from overspray and final cleaning rinse processes.

COVERAGE: 75 - 200 sq.ft. p/gallon depending on coating thickness being removed.

DWELL TIME: 3 minutes to 6 hours depending on coating type and thickness.

APPLICATION: Use an airless sprayer with a 17-21 tip, brush, putty knife or squeegee. 1) Thoroughly clean and degrease the surface with EcoBest™ CMW Cleaner or similar prior to application to allow unobstructed penetration of the coating. 2) Apply enough solution to keep the entire surface evenly saturated during the dwell period. The amount of solution must always be greater than the thickness of the material being removed. 3) Inspect delicate surfaces such as veneers every 10 minutes, otherwise check every 1 hour. If the coating does not remove easily allow longer dwell time. If extended dwell time is needed in warmer outdoor conditions, cover the solution with a plastic drop cloth. Let the solution do the work!

REMOVAL & CLEANING: Remove all coatings and solution with applicable scraper or other stripping tool. Thoroughly clean remaining residue with EcoBest™ CMW Cleaner using a scrub brush, power washer, floor machine, and wet vacuum as applicable. Dispose of all residue in accordance with local disposal regulations.

WARNING: If you scrape, sand or remove old paint, you may release lead dust. Contact the EPA Lead Information Hotline at 1-800-424-LEAD or visit www.epa.gov/lead for information.